

ADDENDUM NO. 1

OCTOBER 4, 2023

RFP 03-23-24

SCCOE HVAC PREVENTATIVE & enteliWEB MAINTENANCE SERVICES

FOR

THE SANTA CLARA COUNTY OFFICE OF EDUCATION

This addendum forms as a part of the Bid Documents for the aforementioned project and modifies the original project specifications as noted below. Kindly acknowledge receipt of this addendum in your proposal. **Failure to do may subject your response to disqualification.**

Part 1: Equipment List

- Attached is the Equipment List for Ridder Park (4 pages total)

Ridder Park	Both N & S	Elkay Drinking fountains	model LZS8WSSP	Filter 51300C	7 units total	Intalled starting 3/2019
			BAC VC1-185/P Ser.			4/27/2022 Tower flushed out new
Ridder Park	North	Evaporative Condenser	U095315201		(3) B-101	level probe ordered.
Ridder Park	North	Open Drive Compressor #1				New Compressor installed 3/2019
				1		Rebuilt motor Palo Alto Electric
		Lincoln 125 hp electric	Lincoln 125hp 1770rpm			11/20/2018 New coupling and laser
Ridder Park	North	motor #1	405ts frame			alignment 3/6/19
			Carrier 5H86-389 Ser.			<u> </u>
Ridder Park	North	Open Drive Compressor #2	1589502296			New Compressor startup 3/2019
		Lincoln 125 hp electric	Lincoln 125hp 1770rpm			3/7/2019 Motor rebuilt new
Ridder Park	North	motor #2	405ts frame			bearings, laser alignment
			RBI model MB1250 Ser.		New Recirc pump	
Ridder Park	North	Hot Water Boiler RBI	081983627		Armstrong on 10/4/21	New RBI Boiler installed 9/14/2019
				1.5 hp Baldor		New Brngs and seals Dec 9 2022,
Ridder Park	North	Boiler Circ Pump	Paco 16 20705-100161 15	motor		seal kit PS200 gasket 11001259
			Lincoln 100vp motor, new			New Merv 13 Filters installed
Ridder Park	North	Hot Deck fan	speed drive 6/11/21	16) 24x24x2	(5) B-105	10/5/2021
				- /		New Merv 13 Filters installed
Ridder Park	North	Cold Deck fan		36) 24x24x2	(6) C-173	10/5/2021
Ridder Park	North	VFD	new speed drive 6/1/21		Lincoln 100 hp motor	
Distate a Deale	N I					Sprayed linkages on vanes
	North	Economizer Section			0) 4)/ 50	2/14/2017
Ridder Park	North	Exhaust fan #1			2) AX-58	New Belts 10/27/2016
Ridder Park	North	Exhaust fan #2			2) AX-58	New Belts 10/27/2016
Ridder Park	North	Exhaust fan #3			2) AX-58	New Belts 6/5/2017
Ridder Park	North	Restroom Exhaust Fan			1) AX-30	
				New battery	.,	
			Model 30R0ZJ71 Ser.	installed	Full service done with load	
Ridder Park	North	Kohler Generator	263061	7/9/2019	test on 4/6/2022	installed in 1990
				New Batteries		
			Model 300DFML Ser.	installed	Full service done with load	
Ridder Park	North	Onan Generator	L880186102	3/7/2019	test on 4/5/2022	Installed New 1988
Ridder Park	Selpa Room	Fan Coil		1) 20x20x1		Not in use
Ridder Park		Condensing Unit				Not in use
						Now Many 12 Filters 10/5/2024 Now
Diddor Dort	Lobby unit North	Dookogo unit roofter	Carrier 48HGD024AB- 611AG Ser. 2306G40027	0) 16,05,0		New Merv 13 Filters 10/5/2021 New
Ridder Park	side	Package unit - rooftop	011AG Sel. 2300G40027	9) 16x25x2	(1) BX-46	Shaft and Bearings 5/11/2011 New @ Oct 2014 Freon 407C,
	New Computer		Model VFS-120-DW-AWS-		Complete service done by	filters new 6/4/21 new steam pots
Ridder Park	Room	Stulz Crac No.2	D-EC Serial 10025256	4) 13.5X31x4	ESI on 4/16/22	6/1/17
			D-LO Senai 10023230	+/ 13.37.31.74	LOI 011 4/ 10/22	0/1/1/

						New @ Oct 2014 Freon 407C,
Ridder Park	New Computer Room	Stulz Crac No.1	Model VFS-120-DW-AWS- D-EC	4) 13.5X31x4	Complete service done by ESI on 4/16/22	filters new 6/4/21 new steam pots 6/1/17
Ridder Park	Computer Room Chiller #1	Carrier 30RAP0306KA08F54	Model 30RAP0306KA08F54 Serial #3814Q51808		Complete service done by ESI on 4/16/22	New @ Oct 2014 Washed Condenser 4/11/2023
Ridder Park	Computer Room Chiller #2	Carrier 30RAP0306KA08F54	Model 30RAP0306KA08F54 Serial #3814Q51840		Complete service done by ESI on 4/16/22	New @ Oct 2014 Washed Condenser 4/11/2023
Ridder Park	Computer Room Chiller #3	Carrier 30RAP0306KA08F54	Model 30RAP0306KA08F54 Serial #3814Q51800		Complete service done by ESI on 4/16/22	New @ Oct 2014 Washed Condenser 4/11/2023
Ridder Park	Computer Room Chp #1	Bell and Gossett E1510 mo. 2AD 5.5 SSF	B & G Pump Motor is a Baldor 7.5hp			New units @ oct 2014, Replaced unit @ 2023
Ridder Park	Computer Room Chp #2	Bell and Gossett E1510 mo. 2AD 5.5 SSF	B & G Pump Motor is a Baldor 7.5hp			New units @ oct 2014, Replaced unit @ 2021
Ridder Park	Delta control system	Panel 900 South building				New communications board installed 7/24/13
Ridder Park	Delta control system	Panel 1000 Noth building			New battery in Solah 850A UPS 4/13/23	New Main Base board installed 2/13/2017
Ridder Park	South Glass Server Rm.	Samsung cooling unit	Model AR24KSFPDWQNCV	Serial 0FZRPAJH600 198A	Refrig 410A 101 oz.	New Unit installed10/17/2017
Ridder Park	South Glass Server Rm.	Samsung Condensing unit	Model AR24KSFPDWQX	Serial	Refrig 410A 101 oz.	New Unit installed 10/17/2017
Ridder Park	Warehouse	Furnace Unit	Reznor mo.CRGBL 400-52 ser. 3AUL8400F17	Washable metal filters		Not in use
Ridder Park	Warehouse	Phone Room	Carrier 50GS - 024 - 301 S/N 1102G30908	1) 20x28x1	Direct drive	New Filter 6/22/2021
Ridder Park	Printshop office (north)	Package unit - rooftop	Trane YHC060A4EMAOE02A000 000000 S/N 202100645L	2) 20x30x1	(1)AX-26	Belt still ok, washed fresh air screen and coil 6/22/21
Ridder Park	Printshop Office links (South)	Package unit - rooftop	Trane YHC048A4EMAOB2A0000 00000 S/N 202100602L	2) 20x25x1	(1)AX-26	Belt still ok, washed fresh air screen and coil 6/22/21
Ridder Park	Printshop Office links (North)	Package unit - rooftop	Carrier 48HJD005-631 S/N 2501G21178	2) 16x25x2	4L380	Belt still ok, washed fresh air screen and coil 6/22/21
Ridder Park	Print Shop (North)	Package unit - rooftop	Carrier 48HJD005-631 S/N 1700G23593	2) 16x25x2	4L380	Belt still ok, washed fresh air screen and coil 6/22/21
Ridder Park	Print Shop (Center)	Package unit - rooftop	Carrier 48HJE004-641 S/N 4001G23478	2) 16x25x2	4L380	Belt still ok, washed fresh air screen and coil 6/22/21

			Trane -			
	Vehicle Service		4WCC4024A1000AB S/N		Direct drive	New unit installed 1/13/23 by foothill
Ridder Park	Area	Package unit - rooftop	223915839L		R410A 5lb 11 oz.	A/C
	Fitness Center AH-		Carrier- 48HIF009-651 S/N			Belt still ok, washed fresh air screen
Ridder Park	1	AH-2 Package unit - rooftop		4) 20x20x2	1) A51	and coil 6/22/21
Ridder Park	Print Shop	AH-1 Package unit - rooftop	Carrier-48HJD012-671	4) 20x20x2	1) A51	Belt still ok, washed fresh air screen and coil 6/22/21
		All-TT ackage unit - Tooltop		4) 2012012		
	Print Shop		Greenheck GB-189-			
Ridder Park	Restrooms	Exhaust fan	3-X ser. 11136371-0712		1) AX-29	New Belt 1/30/2018
	Warehouse/					
Ridder Park		Make-up Air Unit			Refrig 4NotA Not1 oz.	Not in use
	Warehouse/		Donaldson Ventalators		1) A-72 Greased on	New bearings installed on New
Ridder Park	Printshop	KEF-1 Kitchen exhaust fan	RH24D Greenheck RSF1520	460v	8/2/23	Shaft 82010 new belt 7/2015
Ridder Park	Cafeteria Roof	MU-1 Makeup air unit	ser.692950	4) 20x25x1	1) 4L630	unit turned off 10/16
		All Equipment in the				
Ridder Park	Cafeteria	Cafeteria				
	Cafeteria back		Mo. Mim650N Ser.	Ref. 404A 43		Installed new on 3/16/2019 Cleaned
Ridder Park	room	Maxx ICE	06500717013	oz.	Refrig 43A 31 oz.	on 3/6/2020
Ridder Park	Cafeteria	laundry Room Exhaust Fan			Refrig 42018A 20181 oz.	New Motor installed 2018
Ridder Park	Warehouse	Restroom Exhaust Fan			Refrig 44A 41 oz.	New motor installed 4/4/2019
Ridder Park	Warehouse	Warehouse				
Ridder Park	South	Evaporative Condenser	BAC VC1-165 Ser. U037404101MAD	New pump 4/23/10	(2) B-108 Flushed tower 5/15/23	2/11/2011 New Belts installed. New complete pump installed 9/14/22,
	South		0037404101WAD	4/23/10	5/15/25	Installed new on 7/9/10, Laser
			Carrier 5H86-A219			alignment 3/6/19 New Freon
Ridder Park	South	Open Drive Compressor #1	SER.4907UA6957		Refrig 22 150 lbs	10/14/19
			Lincoln/Frame 404TS -			
Ridder Park	South	100 HP Motor #1	2619789			Motor bearings replaced 3/6/19
Ridder Park	South	Open Drive Compressor #2	Carrier 5H86-A219 SER.3415UA8966		Refrig 22 150 lbs	New compressor as of 7/28/2016 Laser Alignment 3/6/19 New freon 10/14/19
Ridder Park	South	100 HP Motor #2	Lincoln/Frame 404TS - 3598528			
Ridder Park	South	VFD	Toshiba FLOWQ20410K - S/N93X29284			Nakin Rep. Randy 568-4817
Ridder Park	South	Exhaust Fan #1			1) B-59	
Ridder Park	South	Exhaust Fan #2			1) B-59	
Ridder Park	South	Exhaust Fan #3			1) B-59	
Ridder Park	South	Exhaust Fan #4			1) B-59	

			RBI reheat boiler Mo. MB1250 Ser.			9/25/19 Compete service by SJ
Ridder Park	South	Hot Deck Boiler	110644473		Refrig 49A 91 oz.	boiler
Ridder Park	South	Hot Water Pump				
-			Trane/CAFB24C12BA2600			New motor 8/6/2019 2/18/2020 New
Ridder Park	South	Hot Deck fan	00	12) 20x25x2	5) BX-90	Merv 13 Filters 7/20/20
Ridder Park	South	Hot Deck Fan motor 15 HP	Lincoln/Frame 254T- S/N2502698			New Bearings installed and new belts 12/11/17
Ridder Park	South	Cold Deck fan	Trane/CF844C21BA26000 0 - S/N NP-1-302KP	32) 24x24x4		New Merv 13 Filters 7/20/20
Ridder Park	South	Cold Deck Evap				Rubberized pans 9/4/16
Ridder Park	South	Cold Deck Fan Motor	Lincoln TV-4730A1 ser. U1930806515		7) C-120	Flushed bearing box new grease put in and cleaned both bearings2/22
Ridder Park	South	Economizer Section				
Ridder Park	South	Restroom Exhaust Fan			1)4L270	New Belt 3/28/22 New motor 10/28/15
Ridder Park	South - TV Studio	Trane	Mo. 4WCC4024A1000AB SER. 223915839L		1) 19.5x 28x 2	
Ridder Park	South - Studio	Fan Coil				
Ridder Park	South - Lobby	Condensing Unit	Carrier/38YH48610DL - S/N 5189E25643			
Ridder Park	South - Lobby	Samsung cooling unit	Samsung AS24A2RC	Washable filters		4/4/2011 new compressor installed R22 unit