## **ADDENDUM #3**

October 10, 2023

RFP03-23-24

## SCCOE HVAC PREVENTATIVE & enteliWEB MAINTENANCE SERVICES

This Addendum forms a part of the RFP Documents for above project and modifies the original project specifications as noted below. Please Acknowledge receipt of this Addendum in your Propsal Form. Failure to do so may subject your response to disqualification.

<u>Part#1 – Addendum#3:</u> Per Addendum#2, the RFP Response Due Date was change from Wednesday, October 11, 2023 to Friday, October 20, 2023 at 3:00 p.m.

Part#2 - Addendum#3: Please see attached updated Equipment List/Task List file.

<u>Part#3 – Addendum#2:</u> Please note below a compilation of all inquiries submitted by multiple vendors, along with their corresponding responses in Red:

## **HVAC RFP03-23-24 Questions & Answers**

- 1) To ensure everyone is bidding apples to apples, is there a tasking list for the equipment listed in Addendum NO. 1 that we should follow? The updated equipment list includes required tasks for each piece of equipment.
- 2) Does the contractor have to have in-house capability to work on the Delta Controls Building Automation System? Yes, the contractor will need to access the system.
- 3) Regarding the scope of work item #3, is the County of Santa Clara asking "Does the contract have these capabilities?" If not, please clarify the scope of work or confirm if they are asking if the contractor has the capability to perform work at other locations in the County. The Santa Clara County Office of Education maintains various sites throughout Santa Clara County. The contractor would have the opportunity to provide services to these sites at hourly rates specified on page 13 of the RFP under "Schedule of Fees."
- 4) Along with the services performed, are you looking for consumables such as filters, belts, and miscellaneous items to be included as well? If so, what would be the frequency of changing the filters and belts of the equipment? This RFP does not include consumables.
- 5) Can you please provide attachments A-H as listed in the Table of Contents online item #4? The RFP does contain attachments A-H starting from Page 16 of the RFP and the following pages. Please check: <a href="https://www.sccoe.org/depts/bizserv/purchasing/Pages/Bids-Posting-System.aspx">https://www.sccoe.org/depts/bizserv/purchasing/Pages/Bids-Posting-System.aspx</a>

- 6) What does the one-time evaluation charge entail? This charge would be for the contractor's initial inspection of the existing equipment.
- 7) What does the one-time cost to establish monitoring connections entail? This charge would be for costs associated for the contractor to initially connect to the Delta Controls Building Management System.
- 8) What does the Weekend Services entail? Weekend services would include the overtime rate for Saturday & Sunday work.
- 9) What is the anticipated award date for this contract? The extended RFP response date is October 20, 2023, thus we will do our review and evaluation the week of October 23 and soon after announce the award.
- 10) Can you please provide Controls As-Builts for the building? These documents are not available.
- 11) Can you please provide the current enteliWEB Version Number and the current capacity of the enteliWEB Server? The current version is 4.24.239; we are unable to provide the current capacity of the server.

++ END OF ADDENDUM THREE++

Jas Sohal

Manager, Purchasing Services

|   |                       |   | T  |                     | T                              | T   |  |
|---|-----------------------|---|--|---------------------|--------------------------------|---|--|
|   |                       |   | BAC VC1-185/P Ser.                                 |                     |                                | 4/27/2022 Tower flushed out. New water probe            |  |
| Ridder Park                             | North Penthouse       | <b>Evaporative Condenser</b>                          | U095315201   |                     | (3) B-101                      | installed.  | 90 day interval (grease bearings, check belts), yearly flush for tower, check spargers.  |
|   |                       | Open Drive Compressor                                 |  |                     |                                |   |  |
| Ridder Park                             | North Penthouse       | #1  |  |                     |                                | New Compressor installed 3/2019                         | 90 day interval (run compressor, monitor bearing noise, etc ) visual leak check, clean units.  |
| 111111111111111111111111111111111111111 |                       | Lineala 405 lan aleatair                              | Line als 405kg 4770mg 4054a                        |                     |                                | ·   | 35 day interval (run compressor, moment searing noise, etc.) visual reak eneak, dean units.  |
| Didden Denk                             |                       | Lincoln 125 hp electric                               | Lincoln 125hp 1770rpm 405ts                        |                     |                                | Rebuilt motor Palo Alto Electric 11/20/2018 New         |  |
| Ridder Park                             | North Penthouse       |   | frame  |                     |                                | coupling and laser alignment 3/6/19                     | 90 day interval (check motor for vibration, wipe down case, check hardware.)   |
|   |                       | Open Drive Compressor                                 | Carrier 5H86-389 Ser.                              |                     |                                |   |  |
| Ridder Park                             | North Penthouse       | #2  | 1589502296   |                     |                                | New Compressor startup 3/2019                           | 90 day interval (run compressor, monitor bearing noise, etc ) visual leak check, clean units.  |
|   |                       | Lincoln 125 hp electric                               | Lincoln 125hp 1770rpm 405ts                        |                     |                                |   |  |
| Ridder Park                             | North Penthouse       | motor #2  | frame  |                     |                                | 3/7/2019 Motor rebuilt new bearings, laser alignment    | 90 day interval (check motor for vibration, wipe down case, check hardware.)   |
|   |                       |   | RBI model MB1250 Ser.                              |                     | New Recirc pump Armstrong on   | <b>3</b> /  |  |
| Ridder Park                             | North Penthouse       | Hot Water Boiler RBI                                  | 081983627  |                     | 10/4/21                        | New RBI Boiler installed 9/14/2019                      | 90 day interval (check condition, check for leaks, monitor loop chemical.)   |
| Triddor F drik                          | Ttorair i ominouco    | THOU WALCH BOHOL INDI                                 | 1000021  |                     | 107-1721                       |   |  |
|   |                       |   |  |                     |                                | New Brngs and seals Dec 9 2022, seal kit PS200 gasket   |  |
| Ridder Park                             | North Penthouse       | Boiler Circ Pump                                      | Paco 16 20705-100161 15                            | 1.5 hp Baldor motor |                                | 11001259  | 90 day interval (note issues or noise, bearings, wipe pump, monitor loop pressure.)  |
|   |                       |   | Lincoln 100vn meter new                            |                     |                                |   |  |
| Ridder Park                             | North Penthouse       | Hot Dock fon  | Lincoln 100vp motor, new speed drive 6/11/21       | 16) 24x24x2         | (5) B-105                      | New Merv 13 Filters installed 10/5/2021                 | 00 day interval (about around duive in electric years, greens for beguings, about mater balts)   |
| Riddel Falk                             | North Penthouse       | HOL DECK IAII   | speed drive 6/11/21                                | 10) 2432432         | (3) B-103                      | New Merv 13 Filters installed 10/3/2021                 | 90 day interval (check speed drive in electric room, grease fan bearings, check motor, belts.)   |
|   |                       |   |  |                     |                                |   |  |
| Ridder Park                             | North Penthouse       | Cold Deck fan   |  | 36) 24x24x2         | (6) C-173                      | New Merv 13 Filters installed 10/5/2021                 | 90 day interval (hot and cold deck grease fans, chk coils and refrig valves)   |
|   |                       |   | ABB speed drive for BAC                            | ABB speed drive for | Lincoln 100 hp motor Cold deck |   |  |
| Ridder Park                             | North Penthouse       | VFD speed drives qty 3                                | Cooling tower fan.                                 | Hot deck motor      | new speed drive 6/1/21         |   | 90 day interval (check belts, vfd motor drive, clean motor and area.)  |
|   |                       |   |  |                     |                                |   |  |
| Ridder Park                             | North Penthouse       | Economizer Section                                    |  |                     |                                | Sprayed linkages on vanes 2/14/2017                     | 90 day interval (check linkage movement, lube linkages with graphite spray.)   |
| <b></b>                                 | N 41 5 41             | <b>-</b> 1  |  |                     | 0) 4 / 50                      | N D II 40/07/0040                                       |  |
| Ridder Park                             | North Penthouse       | Exhaust fan #1  |  |                     | 2) AX-58                       | New Belts 10/27/2016                                    | 90 day interval (check belts, grease bearings, check operation.)   |
| Ridder Park                             | North Penthouse       | Exhaust fan #2  |  |                     | 2) AX-58                       | New Belts 10/27/2016                                    | 90 day interval (check belts, grease bearings, check operation.)   |
| Triduct Func                            |                       |   |  |                     |                                |   | Jo day interval (effects belts), grease bearings, effects operations)  |
| Ridder Park                             | North Penthouse       | Exhaust fan #3  |  |                     | 2) AX-58                       | New Belts 6/5/2017, new bearings , belts 5/23           | 90 day interval (check belts, grease bearings, check operation.)   |
|   |                       |   |  |                     |                                |   | ,  |
| Ridder Park                             |                       | Restroom Exhaust Fan                                  | Dome Fan near Satelite dish                        |                     | 1) AX-30                       |   | 90 day interval (check belts, check operation.)  |
|   | Lobby unit North      |   | Carrier 48HGD024AB-611AG                           |                     |                                | New Merv 13 Filters 10/5/2021 New Shaft and Bearings    |  |
| Ridder Park                             | side                  | Package unit - rooftop                                |  | 9) 16x25x2          | (1) BX-46                      | 5/11/2011   | 90 day interval (check belts, check fresh air screens.)  |
|   | Dolto control         | Panel 900 South building location 1st flr. Electrical |  |                     |                                |   |  |
| Ridder Park                             |                       | room  |  |                     |                                | New battery in Solah 850A UPS 4/13/23                   | 00 deviatement (visite equate 1et floories legatives)  |
| Riduel Falk                             |                       | Panel 1000 North                                      |  |                     |                                | New Dattery III Solali 830A OFS 4/13/23                 | 90 day interval (units south 1st floor electrical room, check ups, operational status.)  |
|   |                       | building Penthouse                                    |  |                     |                                | New Main Base board installed 2/13/2017 New             |  |
| Ridder Park                             |                       | electrical room                                       |  |                     |                                | communications board installed 7/24/2013                | 90 day interval (units north penthouse electrical room, operational status.)   |
|   |                       |   |  |                     |                                |   | , and the second |
|   | South 1st flr         |   |  | Serial              |                                |   |  |
| Ridder Park                             | Glass Server Rm.      | Samsung cooling unit                                  | Model AR24KSFPDWQNCV                               | 0FZRPAJH600198A     | Refrig 410A 101 oz.            | New Unit installed10/17/2017                            | 90 day interval (check operational status of unit.)  |
|   | 0                     | 0   |  |                     |                                |   |  |
| Distance Devil                          |                       | Samsung Condensing                                    | Model ADOMOSDOWSY                                  | Carial              | Defining 4404 404 5            | Nov. Unit in along was are                              |  |
| Ridder Park                             | Glass Server Rm.      | unit out front  | Model AR24KSFPDWQX<br>Carrier 50GS - 024 - 301 S/N | Serial              | Refrig 410A 101 oz.            | New Unit in glass room;                                 | 90 day interval (check condenser on unit out front)  |
| Ridder Park                             | Warehouse             | Phone Room  |  | 1) 20x28x1          | Direct drive                   | New Filter 8/22/2023                                    | 90 day interval (check helt, check fresh sir serson )  |
| NIGUEL FAIR                             | Printshop office      | I HOHE MOUIII   | Trane  | 1, 20,20,1          | Direct direc                   | INCW I IIIGI UIZZIZUZJ                                  | 90 day interval (check belt, check fresh air screen.)  |
|   | (north) small         |   | YHC060A4EMAOE02A0000000                            |                     |                                |   |  |
| Ridder Park                             | •                     | Package unit - rooftop                                |  | 2) 20x30x1          | (1)AX-26                       | Belt still ok, washed fresh air screen and coil 6/22/23 | 90 day interval (check belt, check fresh air screen.)  |
|   | Printshop office      | <u>-</u> '  | Trane  |                     |                                |   | ,  |
|   | (south) small         |   | YHC048A4EMAOB2A00000000                            |                     |                                |   |  |
| Ridder Park                             |                       | Package unit - rooftop                                |  | 2) 20x25x1          | (1)AX-26                       | Belt still ok, washed fresh air screen and coil 6/22/23 | 90 day interval (check belt, check fresh air screen.)  |
|   | Printshop Office      |   | Carrier 48HJD005-631 S/N                           |                     |                                |   |  |
| Ridder Park                             |                       | Package unit - rooftop                                |  | 2) 16x25x2          | 4L380                          | Belt still ok, washed fresh air screen and coil 6/22/23 | 90 day interval (check belt, check fresh air screen.)  |
| Didder Derle                            | Print Shop            | Dookogo unit vaattan                                  | Carrier 48HJD005-631 S/N                           | 2) 46×25×2          | 41.290                         | Polt still alt woohed fresh sin severe and sell closure |  |
| Ridder Park                             | (North)<br>Print Shop | Package unit - rooftop                                | 1700G23593<br>  Carrier 48HJE004-641 S/N           | 2) 16x25x2          | 4L380                          | Belt still ok, washed fresh air screen and coil 6/22/23 | 90 day interval (check belt, check fresh air screen.)  |
| Ridder Park                             | -                     | Package unit - rooftop                                |  | 2) 16x25x2          | 4L380                          | Belt still ok, washed fresh air screen and coil 6/22/23 | 90 day interval (check belt, check fresh air screen.)  |
| Made I alk                              | Vehicle Service       | i donage unit - roonop                                | Trane - 4WCC4024A1000AB                            | -, IUALUAL          | Direct drive R410A 5lb 11      | Bon Still On, Washieu Heshi ali Scieen aliu Coli WZZIZS | 30 day interval (check beit, check fresh all screen.)  |
| Ridder Park                             |                       | Package unit - rooftop                                | S/N 223915839L                                     |                     | oz.                            | New unit installed 1/13/23 by foothill A/C              | 90 day interval (check belt, check fresh air screen.)  |
|   |                       | AH-2 Package unit -                                   | Carrier- 48HIF009-651 S/N                          |                     |                                |   | ,  |
| Ridder Park                             |                       | rooftop   |  | 4) 20x20x2          | 1) A51                         | Belt still ok, washed fresh air screen and coil 6/22/23 | 90 day interval (check belt, check fresh air screen.)  |
| L                                       |                       | <del>-</del>  | •  |                     |                                | <del>,</del>  |  |

|             |                         | AH-1 Package unit -            | Carrier-48HJD012-671 ser.                  |                    | <u></u>                   |   |   |
|-------------|-------------------------|--------------------------------|--|--------------------|---------------------------|---|---|
| Ridder Park | Print Shop              | rooftop                        | 3707G20771                                 | 4) 20x20x2         | 1) A51                    | Belt still ok, washed fresh air screen and coil 6/22/23             | 90 day interval (check belt, check fresh air screen.)   |
| Ridder Park |                         | Exhaust fan                    | Greenheck GB-189-3-X ser. 11136371-0712    |                    | 1) AX-29                  | New Belt 1/30/2018  | 90 day interval (check belts.)  |
| Ridder Park | Warehouse/<br>Printshop | KEF-1 Kitchen exhaust fan      | Donaldson Ventalators<br>RH24D             | ser. 7946 1hp 460v | 1) A-72 Greased on 8/2/23 | New bearings installed on New Shaft , new belts 8/2023              | 90 day interval (check belts.)  |
| Ridder Park | Cafeteria Roof          | MU-1 Makeup air unit           | Greenheck RSF1520<br>ser.692950            | 4) 20x25x1         | 1) 4L630                  | not in service as of 10/2016  |   |
| Ridder Park | Cafeteria               | All Equipment in the Cafeteria |  | ,                  | ,                         | hobarts, traulsen, atosa units                                      | 90 day interval (Check all freezers, refrigerators, ice maksers, broilers, fryers, ovens, stove.) |
| Ridder Park | Cafeteria back          | Maxx ICE                       | Mo. Mim650N Ser.<br>06500717013            |                    | Ref. 404A 43 oz.          | Installed new on 3/16/2019 Cleaned on 3/6/2023                      | 90 day interval (check water filters , cleaning status, )   |
| Ridder Park | Wash Room               | laundry Room Exhaust           |  |                    |                           | New Motor installed 2018  |   |
|             |                         |                                |  |                    |                           |   | 90 day interval (check air exiting fan on roof )  |
| Ridder Park | Warehouse               | Restroom Exhaust Fan           |  |                    |                           |   | 90 day interval (check belt on unit.)   |
| Ridder Park | South Penthouse         | Evaporative Condenser          | BAC VC1-165 Ser.<br>U037404101MAD          | 2) B-108 Vbelts    | Flushed tower 5/15/23     |   | 90 day interval (grease bearings, check belts, vane control on tower.)                            |
|             |                         | Open Drive Compressor          |  |                    | !!                        | Installed new on 7/9/10, Laser alignment 3/6/19 New                 |   |
| Ridder Park | South Penthouse         | #1                             | SER.4907UA6957                             |                    | Refrig 22 280 lbs         | Freon 10/14/19  | 90 day interval (check control status, oil level, block heaters,wipe down unit.)                  |
| Ridder Park | South Penthouse         |                                | Lincoln/Frame 404TS - 2619789              |                    |                           |   | 90 day interval (check motor for vibration, wipe down case, check harware.)                       |
|             |                         | , .                            | Carrier 5H86-A219                          |                    |                           | New compressor as of 7/28/2016 Laser Alignment 3/6/19               |   |
| Ridder Park | South Penthouse         | #2                             | SER.3415UA8966                             |                    | Refrig 22 250 lbs         | New freon 10/14/19  | 90 day interval (check control status, oil level, block heaters,wipe down unit.)                  |
| Ridder Park | South Penthouse         | 100 HP Motor #2                | Lincoln/Frame 404TS - 3598528              |                    |                           |   | 90 day interval (check motor for vibration, wipe down case, check harware.)                       |
| Ridder Park | South Penthouse         | VFD                            | Toshiba FLOWQ20410K -<br>S/N93X29284       |                    |                           |   |   |
| Ridder Park | South Penthouse         | Exhaust Fan #1                 |  |                    | 1) B-59                   |   | 90 day interval (check belts, grease bearings, check operation.)                                  |
| Ridder Park | South Penthouse         | Exhaust Fan #2                 |  |                    | 1) B-59                   |   | 90 day interval (check belts, grease bearings, check operation.)                                  |
| Ridder Park | South Penthouse         | Exhaust Fan #3                 |  |                    | 1) B-59                   |   | 90 day interval (check belts, grease bearings, check operation.)                                  |
| Ridder Park | South Penthouse         |                                | RBI reneat boiler Mo. MB1250               |                    | 1) B-59                   |   | 90 day interval (check belts, grease bearings, check operation.)                                  |
| Ridder Park | South Penthouse         |                                | Ser. 110644473                             |                    |                           | 9/25/19 Compete service by SJ boiler                                | 90 day interval (check condition, check for leaks, monitor loop chemical.)                        |
| Ridder Park | South Penthouse         | Hot Water Pumps                |  |                    |                           |   | 90 day interval (check for leaks on all 3 pumps for system operational.)                          |
| Ridder Park | South Penthouse         | Hot Deck fan                   | Trane/CAFB24C12BA260000                    | 12) 20x25x2        | 5) BX-90                  |   | 90 day interval (check belts, grease bearings, check operation.)                                  |
| Ridder Park | South Penthouse         | Hot Deck Fan motor 15<br>HP    | Lincoln/Frame 254T-<br>S/N2502698          |                    |                           | New Bearings installed and new belts 12/11/17                       | 90 day interval (check motor for vibration, wipe down case, check linkages.)                      |
| Ridder Park | South Penthouse         | Cold Deck fan                  | Trane/CF844C21BA260000 -<br>S/N NP-1-302KP | 32) 24x24x4        |                           | New Merv 13 Filters 7/20/20   | 90 day interval (hot and cold deck grease fans , chk coils and refrig valves , )                  |
| Ridder Park | South Penthouse         | Cold Deck Evap                 |  |                    |                           | Rubberized pans 9/4/16  | 90 day interval (check drain coil drain pans and drains.)   |
| Ridder Park |                         | Cold Deck Fan Motor            | Lincoln TV-4730A1 ser.<br>U1930806515      |                    | 7) C-120                  | Flushed bearing box new grease put in and cleaned both bearings2/22 | 90 day interval ( check coils and refrig valves , )   |
| Ridder Park |                         | Economizer Section             |  |                    |                           |   | 90 day interval (check linkage movement, lube linkages with graphite spray.)                      |
| Ridder Park |                         | Restroom Exhaust Fan           |  |                    | 1)4L270                   | New Belt 3/28/22 New motor 10/28/15                                 |   |
| Niduel Fark |                         |                                | M. 4W0040044460047                         |                    | 1,44210                   | New Deit 3/20/22 New Hibtor 10/20/13                                | 90 day interval (check belts, check operation.)   |
| Ridder Park | South - TV<br>Studio    |                                | Mo. 4WCC4024A1000AB<br>SER. 223915839L     |                    |                           | Non rebuildable Compressor unit non functional now.                 | System is down currently  |
| Ridder Park | South - Studio          | Fan Coil                       |  |                    |                           |   | Fan operational in ceiling 1st floor hallway near front building marked on t-bar.                 |
| Ridder Park | South - Lobby           | Condensing Unit                | Carrier/38YH48610DL - S/N<br>5189E25643    |                    |                           |   | Not in use  |
| Made I alk  | Journ - Lobby           | Solidonaling Offic             | 0100000                                    | +                  |                           |   | NOT III USC   |
| Ridder Park | South - Lobby           | Samsung cooling unit           | Samsung AS24A2RC                           | Washable filters   |                           | 4/4/2011 new compressor installed R22 unit                          | Not in use  |
|             |                         |                                |  |                    |                           |   |   |